

組立マンホール会合点 (直交・落差 0cm)

中間点	200	250	300	350	400	450	500	600	700	800	900	1000	1100	1200	1350
200															
250	0号組立マンホール														
300															
350															
400															
450	1号組立マンホール														
500															
600			2号組立マンホール												
700															
800															
900				3号組立マンホール											
1000															
1100															
1200															
1350															

この会合表は、会合角 90 度、落差 0 cm の場合であり、会合角が異なる場合と、落差のある場合は別途検討が必要となる。